Occurrence Notification Email Date (Text)	ATSB Reference Number	ATSB Investigatio n Reference	Team Name	Occurrence Date	Occurrence Category	Occurrence	Occurrence Location State	Occurrence	Latitude (Dec	Occurrence Longitude (Dec Degrees)	Occurrence Summary	ICAO Type Designator (VH Derived)	Registered Operator ARN (VH Derived)	Registration Holder Holder Name (VH Derived)	Registration Type Display (Derived)		Aircraft Type (ATSB Reported)	Aircraft Model (ATSB Reported)
Tue, 14 Jan 2020 16 40 18 +1100	201909255		CNS/ATM - Pool	01/12/2019	Incident	E/GPWS warning	TAS	Hobart Aerodrome	-42.8362	147.5103	During approach, the crew received an E/GPWS PULL UP alert.	B738	s 47G	GAL MSN THREE LIMITED	Australian VH Aircraft	VH-YFV	AEROPLA NE	737-8FE
Thu, 16 Jan 2020 16 40 12 +1100	201909305		Eastern - CMT 1	04/12/2019	Incident	Turbulence/ windshear/m icroburst	TAS	Hobart Aerodrome	-42.8362	147.5103	During approach, the aircraft encountered severe windshear and the crew conducted a missed approach.	B738		JIN SHAN 29 IRELAND COMPANY LIMITED	Australian VH Aircraft	VH-VUB	AEROPLA NE	737-8FE
Wed, 29 Jan 2020 16 40 08 +1100	201909660		CNS/ATM - Pool	21/12/2019	Incident	E/GPWS warning	TAS	Hobart Aerodrome	-42.8362	147.5103	During approach, the crew received an E/GPWS SINKRATE alert.	B738		JIN SHAN 29 IRELAND COMPANY LIMITED	Australian VH Aircraft	VH-VOT	AEROPLA NE	737-8FE
Tue, 24 Dec 2019 16 40 12 +1100	201909106		RPAS -	22/12/2019	Incident	Encounter	TAS	Hobart Aerodrome, 319° T 6Km	-42.7983		During approach, the crew observed a remotely piloted aircraft at the same altitude 50 m to the left of their position.	A320		QANTAS AIRWAYS LIMITED	Australian VH	VH-VGN	AEROPLA NE	A320-232
Wed, 29 Jan 2020 16 40 08 +1100	201909680		RPAS - Pool	22/12/2019	Incident	Encounter w th RPA	TAS	near Hobart Aerodrome	-42.8362	147.5103	Passing 700 ft on approach, the crew observed a remotely piloted aircraft approximately 50 m to the left of the aircraft.	A320		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-VGN	AEROPLA NE	A320-232
Mon, 3 Feb 2020 16 40 18 +1100	201909810		Southern - CMT 1	30/12/2019	Incident	Turbulence/ windshear/m icroburst	TAS	Hobart Aerodrome	-42.8362	147.5103	During approach, the aircraft encountered windshear resulting in an unstable approach. The crew conducted a missed approach.	B712		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-NXQ	AEROPLA	717-200
Mon, 3 Feb 2020 16 40 18 +1100	201909817		Southern -	30/12/2019	Incident	Turbulence/ windshear/m	TAS	Hobart Aerodrome	-42.8362		During initial climb the aircraft encountered windshear and the crew received an E/GPWS WINDSHEAR alert.	A321		QANTAS	Australian VH	VH-VWT	AEROPLA	A321-231
Mon, 3 Feb 2020 16 40 18 +1100	201909829		Eastern - CMT 1	30/12/2019	Incident	Turbulence/ windshear/m	TAS	Hobart Aerodrome, 315° M 56Km	-42.4025	147.1728	During descent, the aircraft encountered turbulence resulting an E/GPWS BANK ANGLE alert.	B738			Australian VH	VH-VZU	AEROPLA	737-838
Tue, 4 Feb 2020 16 40 11 +1100	201909853		CNS/ATM - Pool	31/12/2019	Incident	E/GPWS warning	TAS	Hobart Aerodrome	-42.8362	147.5103	During approach, the crew received an E/GPWS BANK ANGLE	B738		JSA INTERNATIO NAL U.S. HOLDINGS, LLC	Australian VH Aircraft	VH-YFJ	AEROPLA NE	737-8FE
Tue, 4 Feb 2020 16 40 11 +1100	202000170		Unassigned Occurrence s		Incident	Birdstrike	TAS	Cambridge (ALA)	-42.8267	147.4747	During landing, the aircraft struck a bird.				Unknown Registration Type	UNKNOWN	UNKNOW N	UNKNOW N
Thu, 9 Jan 2020 16 40 09 +1100	202000036		CNS/ATM - Pool	05/01/2020	Incident	Infrastructur e - Other	TAS	Hobart Aerodrome	-42.8362	147.5103	During departure, multiple aircraft diverged from the runway centreline.	A320		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-VGU	AEROPLA NE	A320-232
Thu, 13 Feb 2020 16 40 11 +1100	202000449		Southern - CMT 1	12/01/2020	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.8362		During approach, the aircraft struck a seagull.	A320		BOC AVIATION (USA) CORPORATI ON	Australian VH Aircraft	VH-VFK	AEROPLA NE	A320-232
Wed, 12 Feb 2020 16 40 09 +1100	202000416		Unassigned Occurrence s		Incident	Birdstrike	TAS	Cambridge (ALA)	-42.8267	147.4747	During approach, the aircraft struck a bird.				Unknown Registration Type	UNKNOWN	AEROPLA NE	UNKNOW N
Mon, 20 Jan 2020 16 40 15 +1100	202000088		Southern - CMT 1	17/01/2020	Incident	Landing gear/indicati on	TAS	Cambridge (ALA)	-42.8267	147.4747	During approach, the crew received an unsafe landing gear indication.	PA31		AIRLINES OF TASMANIA PTY LTD	Australian VH Aircraft	VH-BTI	AEROPLA NE	PA-31
Tue, 28 Jan 2020 16 40 17 +1100	202000133		Sydney - CMT 1	27/01/2020	Incident	Fuel systems	TAS	Hobart Aerodrome	-42.8362	147.5103	During take-off, the crew received a no. 1 engine fuel filter blocked alert and rejected the take-off.	B462		VANGUARD INVESTMENT S PTY LTD	Australian VH Aircraft	VH-SAZ	AEROPLA NE	BAE 146 SERIES 200
Fri, 14 Feb 2020 16 40 12 +1100	202000483		Eastern - CMT 1	11/02/2020	Incident	Flight control systems	TAS	Hobart Aerodrome	-42.8362	147.5103	During approach, the craw reported a flight control issue and conducted a missed approach. The engineering inspection revealed the leading edge slat micro switch failed which was subsequently replaced.	B738		AWAS 39413 LIMITED	Australian VH Aircraft	VH-YFC	AEROPLA NE	737-81D

											s 47G					
										During approach, the crew reported						
Fri, 14 Feb 2020										they were unable to capture the ILS		QANTAS				
16 40 12 +1100	202000484	Southern - CMT 1	11/02/2020	Incident	Miscellaneo us - Other	TAS	near Hobart Aerodrome	-42.8362	147.5103	glidepath.	B712	AIRWAYS LIMITED	Australian VH Aircraft	VH-YQX	AEROPLA NE	717-200
	202000404	OWIT T	11/02/2020	moldon	us - Outer	IAU	Actodionic	-42.0002	147.0100	During descent,	0/12	BOC	Allolan	THE		717-200
Fri, 14 Feb 2020										fumes were		AVIATION (USA)				
16 40 12 +1100	202000473	Southern - CMT 1	13/02/2020	Incident	Fumes	TAS	near Hobart Aerodrome	-42.8362	147.5103	detected in the cabin and cockpit.	A320	CORPORATI ON	Australian VH Aircraft	VH-VFJ	AEROPLA NE	A320-232
										During approach,						
										the approach became unstable						
										and the primary f ight display failed						
Mon, 17 Feb 2020										and the pilot conducted a		SHORLAND				
16 40 17		Sydney -			Unstable		Hobart			missed approach.		ENTERPRISE	Australian VH		AEROPLA	
+1100	202000509	Pool	13/02/2020	Incident	approach	TAS	Aerodrome	-42.8362	147.5103		TBM7	S PTY LTD	Aircraft	VH-YZZ	NE	TBM 700
										During the routine runway inspection,						
Thu, 26 Mar 2020		Unassigned								the safety officer retrieved a			Unknown			
16 40 11	000004007	Occurrence			D: 1 1 1		Hobart	10,0000	447 5400	shearwater carcass.			Registration		UNKNOW	
+1100 Fri, 27 Mar	202001307	S	16/02/2020	Incident	Birdstrike	TAS	Aerodrome	-42.8362	147.5103				Туре	UNKNOWN	N	
2020 16 40 15		Unassigned Occurrence					Cambridge			During take-off, the aircraft struck			Unknown Registration		AFROPI A	UNKNOW
	202001348	s	17/02/2020	Incident	Birdstrike	TAS	(ALA)	-42.8267	147.4747	a bird.			Туре	UNKNOWN	NE	N
										During climb, the	(70					
Tue, 3 Mar										crew detected a pressurisation	s 47G	JIN SHAN 29				
2020 16 40 17		Eastern -			Air/pressuris		near Hobart			issue and conducted a return		IRELAND COMPANY	Australian VH		AEROPLA	
+1100	202000791	CMT 1	29/02/2020	Incident		TAS	Aerodrome	-42.8362	147.5103	to Hobart.	B738	LIMITED		VH-VOS	NE	737-8FE
Tue, 7 Apr 2020										During landing, the aircraft struck a						
16 40 15 +1000	202001785	Eastern - CMT 1	06/03/2020	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.8362	147.5103		B738	JPA No. 174 CO., LTD.	Australian VH Aircraft	VH-YIB	AEROPLA NE	737-8FE
										D						
										During approach, the aircraft						
										encountered moderate						
Wed, 15 Apr										turbulence and the crew received an		SHORT				
2020 16 40 16		Eastern -			Turbulence/ windshear/m		Hobart			E/GPWS SINK		HAUL 2017 NO. 2 PTY	Australian VH		AEROPLA	
+1000	202001966	CMT 1	13/03/2020	Incident		TAS	Aerodrome	-42.8362	147.5103	RATE alert.	B738	LTD	Aircraft	VH-YFZ	NE	737-800
										During take-off,						
										the aircraft struck a pacific gull and						
										returned the						
Mon, 20 Apr										aircraft to Cambridge. The						
2020 16 40 16		Unassigned Occurrence					Cambridge			aircraft sustained minor damage.			Unknown Registration		AEROPLA	UNKNOW
+1000	202002119	s	23/03/2020	Incident	Birdstrike	TAS	(ALA)	-42.8267	147.4747				Туре	UNKNOWN	NE	N
Thu, 30 Apr 2020										During initial climb, the aircraft struck		AIRLINES OF				
16 40 18		Southern -					Cambridge			a bird.		TASMANIA	Australian VH		AEROPLA	
+1000	202002369	CMT 1	24/04/2020	Incident	Birdstrike	TAS	(ALA)	-42.8267	147.4747		BE76	PTY LTD	Aircraft	VH-MKH	NE	76
										During approach, the crew received						
										an unsafe landing						
										gear indication and conducted a						
Mon, 11 May										missed approach. A faulty globe was						
2020 16 40 17		Southern -			Landing gear/indicati		Cambridge			found to be the cause.		s 47E	Australian VH		AEROPLA	
+1000 Wed, 12	202002515	CMT 1	10/05/2020	Incident	on	TAS	(ALA)	-42.8267	147.4747		BE76		Aircraft	VH-BTO	NE	76
Aug 2020					Landing					During landing, the nose wheel tyre		MULTI-				
16 40 13 +1000	202003983	Eastern - CMT 1	11/08/2020	Incident	gear/indicati on	TAS	Hobart Aerodrome	-42.8362	147.5103	deflated	C441	HAULAGE PTY LTD	Australian VH Aircraft	VH-OXY	AEROPLA NE	441
										During cruise, a practice engine						
										failure was						
										conducted and the no. 1 engine was						
										shut down and the propeller was						
										feathered. Once						
										returning the engine to						
										operation it would only produce						
										partial power. The crew diverted to						
										Hobart and conducted a						
										precautionary						
										landing. The engineering						
										inspection revealed that the						
										fuel shutoff lever						
										for the no. 1						
							Cambridge			engine was in the		JGB				
2020 16 40 20	202004377	Eastern -	04/09/2020	peident	Incorrect	TAS	Cambridge (ALA), 180° M 19Km	12 0070	147 4160	closed position.	s 47G		Australian VH	VH_FHO	AEROPLA	PA-31.335
2020 16 40 20 +1000 Fri, 23 Oct	202004377	Eastern - Pool	04/09/2020	Incident	Incorrect	TAS		-42.9878	147.4163	closed position.	s 47G	HOLDINGS PTY LTD		VH-FHQ	AEROPLA NE	PA-31-325
2020 16 40 20 +1000 Fri, 23 Oct 2020 16 40 13		Pool Southern -			configuration		(ALA), 180° M 19Km Hobart			Closed position. During take-off, the aircraft struck	PA31	HOLDINGS PTY LTD QANTAS AIRWAYS	Aircraft Australian VH		AEROPLA	
Mon, 7 Sep 2020 16 40 20 +1000 Fri, 23 Oct 2020 16 40 13 +1100 Thu, 19 Nov	202004377	Pool	04/09/2020 22/10/2020	Incident	configuration	TAS	(ALA), 180° M 19Km	-42.9878 -42.8362	147.5103	closed position. During take-off, the aircraft struck a swallow.	PA31 A320	HOLDINGS PTY LTD QANTAS AIRWAYS LIMITED	Aircraft		NE	PA-31-325 A320-232
2020 16 40 20 +1000 Fri, 23 Oct 2020 16 40 13		Pool Southern -			configuration		(ALA), 180° M 19Km Hobart		147.5103	Closed position. During take-off, the aircraft struck	PA31 A320	HOLDINGS PTY LTD QANTAS AIRWAYS LIMITED PIONEER AIRCRAFT	Aircraft Australian VH	VH-VQL	AEROPLA	

												s 47G					
Tue, 1 Dec 2020 16 40 16 +1100	202005875	CNS/ATM Pool	27/11/2020	Incident	E/GPWS warning	TAS	near Hobart Aerodrome	-42.8362	147.5103	During approach, the crew received an E/GPWS BANK ANGLE alert.		5 47 G	VIOLIN LEASING CO., LTD.	Australian VH Aircraft	VH-XZJ	AEROPLA NE	737-838
Thu, 3 Dec 2020 16 40 16		Eastern -			Animal		Hobart			During take-off, the aircraft struck			SHORT HAUL 2017 NO. 2 PTY	Australian VH		AEROPLA	
Tue, 15 Dec	202005894	CMT 1	30/11/2020	Incident	strike	TAS	Aerodrome	-42.8362	147.5103	a hare. During take-off, the aircraft struck	B738		LTD	Aircraft	VH-YWA	NE	737-800
	202006149	Southern - CMT 1	11/12/2020	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.8362	147.5103	a welcome	SW4		JAH2VHUUB, Ltd	Australian VH Aircraft	VH-UUB	AEROPLA NE	SA227-DC
Tue, 15 Dec 2020 16 40 15 +1100	202006150	Southern - CMT 1	11/12/2020	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.8362	147.5103	During take-off, the aircraft struck a swallow.	SW4		JAH2VHHWR , Ltd	Australian VH Aircraft	VH-HWR	AEROPLA NE	SA227-DC
Fri, 18 Dec										During initial climb the cabin crew observed smoke	,						
2020 16 40 15 +1100	202006252	CNS/ATM Pool	14/12/2020	Incident	Smoke	TAS	near Hobart Aerodrome	-42.8362	147.5103	emanating from	B738		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-VYZ	AEROPLA NE	737-838
Mon, 21 Dec 2020							Hobart Aerodrome, 205.85° T 9Km (Tasmania			During training, the pilot lost control of the RPA. The RPA collided with terrain resulting in	f .			Unknown		REMOTEL	
16 40 24 +1100	202006265	CNS/ATM Pool	16/12/2020	Accident	Collision w th terrain	TAS	Police Academy)	-42.9087	147.4625					Registration Type	N/A	Y PILOTED AIRCRAFT	
	202006422	Southern - Pool	23/12/2020	Incident	Lost/unsure of position	TAS	Hobart Aerodrome, 360° M 46Km	-42.4333	147.6558	During descent, the aircraft deviated off track and descended below the assigned level. ATC were unable to immediately establish communication was re- established, the aircraft was provided with their position.		s 17G	FUTURISTIC SERVICES PTY. LTD.	Australian VH Aircraft	VH-VME	AEROPLA NE	P.68C
Tue, 5 Jan 2021 16 40 15		Southern -					Hobart			During landing, the aircraft struck a sparrow.	e		UMB BANK, NATIONAL ASSOCIATIO	Australian VH		AEROPLA	
Tue, 5 Jan 2021 16 40 15 +1100	202006450	Eastern - CMT 1	27/12/2020	Incident	Turbulence/ windshear/m icroburst	TAS	Hobart Aerodrome	-42.8362	147.5103	During approach, the crew encountered moderate turbulence and a flap overspeed occurred. The crew received a crew received a crew received a warning and conducted a missed approach during which the crew received a flaps disagree warning.	8738		JPA NO. 124 CO., LTD.	Australian VH Aircraft	ин-лик	AEROPLA NE	737-8FE
Fri, 12 Mar 2021 16 40 17 +1100	202101100	CNS/ATM Pool	22/02/2021	Incident	Avionics/flig ht instruments	TAS	near Hobart Aerodrome	-42.8362	147.5103		BE20		ROYAL FLYING DOCTOR SERVICE OF AUSTRALIA (SOUTH EASTERN SECTION)	Australian VH Aircraft	VH-LTQ	AEROPLA NE	B200C
Wed, 21 Apr 2021 16 40 12 +1000	202102189	CNS/ATM Pool	03/04/2021	Incident	Operational non- compliance	TAS	Hobart Aerodrome, 290° M 28Km	-42.6922	147.2325	During cruise, the crew encountered a severe downdraft and were unable to maintain assigned level.			MEDIKA PTY. LTD.	Australian VH Aircraft	VH-SQZ	AEROPLA NE	182G
Wed, 21 Apr 2021 16 40 12 +1000	202102169	Southern - CMT 1	06/04/2021	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.8362	147.5103		A320		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-VGP	AEROPLA NE	A320-232
Thu, 22 Apr 2021 16 40 12 +1000	202102228	Southern - CMT 1	07/04/2021	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.8362	147.5103	During landing, the aircraft struck a richards pipit.	A321		BOC AVIATION (UK) LIMITED	Australian VH Aircraft	VH-VWN	AEROPLA NE	A321-231
Wed, 14 Apr 2021 16 40 14 +1000	202101797	Unassigne Occurrenc s		Incident	Unforecast weather	TAS	Hobart Aerodrome	-42.8362	147.5103		t			Unknown Registration Type	UNKNOWN	UNKNOW N	UNKNOW N
Thu, 6 May 2021 16 40 11 +1000	202102601	Southern - CMT 1	19/04/2021	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.8362	147.5103	During the pre- flight inspection, evidence of a birdstrike was detected. It could not be determined when the strike occurred.	B712		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-NXM	AEROPLA NE	717-200

Thu, 6 May 2021 16 40 11	202102651	Southern -								During landing /			WELLS FARGO				
Thu, 6 May 2021 16 40 11	202102651						Hobart			During landing, the aircraft struck a masked lapwing.			TRUST COMPANY, NATIONAL ASSOCIATIO			AEROPLA	
2021 16 40 11		CMT 1	22/04/2021	Incident	Birdstrike	TAS	Aerodrome	-42.8362	147.5103		A320		N WOMBAT	Aircraft	VH-VGQ	NE	A320-232
	202102663	Southern - CMT 1	22/04/2021	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.8362	147.5103	During landing, the aircraft struck a bird.	A320		3668 LEASING	Australian VH Aircraft	VH-VQC	AEROPLA NE	A320-232
Wed, 26 May 2021 16 40 11 +1000 20	202103198	Southern - CMT 1	23/05/2021	Incident	Engine failure or malfunction	TAS	Hobart Aerodrome, 225° M 78Km	-43.1833	146.6817	During cruise, the engine lost partial power and the crew conducted a precautionary landing at Glendevie.	C206		SUCCESSFU L DEVELOPME NTS PTY LTD		VH-RGE	AEROPLA NE	U206F
Mon, 7 Jun 2021 16 40 15 +1000 20	202103262	Southern - CMT 1	26/05/2021	Serious Incident	Hard landing	TAS	Cambridge (ALA)	-42.8267	147.4747	The aircraft landed hard resulting in the right main landing gear collapsing and the propeller striking the ground. The aircraft sustained minor damage.				Australian VH Aircraft	VH-BTO	AEROPLA NE	76
Fri, 4 Jun 2021 16 40 15 +1000 20	202103427	Southern - Pool	28/05/2021	Incident	Runway - Other	TAS	Cambridge (ALA)	-42.8267		ATC was unable to contact the pilot to confirm their intentions close to last light. The aircraft arrived after last light and landed at Cambridge without the authority of the airport operator.	t	s 47F		Australian VH Aircraft	s 47F	AEROPLA NE	AEROPRA KT-32
Mon, 7 Jun 2021 16 40 15		CNS/ATM -			Separation		near Hobart	12.020		During intial climb, the crew of the Boeing 717 observed an aircraft tracking towards them and became concerned with the vertical separation. Shortly after the crew received a		s 47G	QANTAS AIRWAYS	Australian VH		AEROPLA	
	202103493	Pool	01/06/2021	Incident		TAS	Aerodrome	-42.8362	147.5103	TCAS TA alert. During a return to	B712				VH-YQX	NE	717-200
Tue, 22 Jun 2021 16 40 17 +1000 20	202103758	CNS/ATM - Pool	19/06/2021	Incident	Collision w th terrain	TAS	Hobart Aerodrome, 293° T 22Km	-42.7578	147.2603	the operator, the RPA lost altitude and impaced trees.				Unknown Registration Type	SCHMITT	REMOTEL Y PILOTED AIRCRAFT	ENTERPRI
Wed, 23 Jun 2021 16 40 12 +1000 20	202103758	CNS/ATM - Pool	19/06/2021	Incident	CFIT	TAS	Hobart Aerodrome, 293° T 22Km	-42.7578		During surveillance operations, the pilot received a low battery warning. The battery level depleted to a critical level and the RPA executed an automatic landing in to trees resulting in minor damage.	,			Unknown Registration Type	N/A	REMOTEL Y PILOTED AIRCRAFT	ENTERPRI
Fri, 2 Jul 2021 16 40 12 +1000 20	202104026	Northern - Pool	20/06/2021	Incident	Warning devices	TAS	near Hobart Aerodrome	-42.8362		During take-off, the crew received a chip warning ligh and the crew condcuted a return to Hobart.	1	s 47G	s 47F	Australian VH Aircraft	VH-UHF	HELICOPT ER	UH-1B
Mon, 5 Jul 2021 16 40 15 +1000 2(202104026	Southern - CMT 1	20/06/2021	Incident	Warning devices	TAS	near Hobart Aerodrome	-42.8362	147.5103	During take-off, the crew received a chip warning ligh and returned the aircraft to Hobart. The engineering inspection revealed a failing mast bearing.	1 B06		ROTOR-LIFT PTY LIMITED		VH-UHV	HELICOPT	2068
Wed, 23 Jun 2021 16 40 12	000402004	Southern -	20/06/2021		Hand June 4	TAC	Hobart	40.0005		The aircraft landed hard.			BCC EQUIPMENT LEASING CORPORATI		VIIVOW	AEROPLA	747.000
Mon, 13 Sep 2021 06 48 51 O	202103831 DA2021-	CMT 1 Western -	20/06/2021	Incident	Hard landing		Aerodrome 0 km 0 degrees from Hobart	-42.8362		During landing, the aircraft struck a cockatoo.				Australian VH	VH-YQW	AEROPLA	717-200
Wed, 29 Sep 2021 02 10 37 O	04513 DA2021-	Pool Southern -	23/07/2021	Incident		TAS	Aerodrome 0 km 0 degrees from Hobart			During landing, the aircraft struck a hare.			QANTAS AIRWAYS	Australian VH	VH-YQU	AEROPLA	717-200
Tue, 30 Nov 2021 05 52 35 O	DA2021- D5224	CMT 1 Eastern - CMT 1	25/07/2021	Incident		TAS	Aerodrome 0 km 0 degrees from Hobart Aerodrome		147.510278	During landing, the aircraft struck a plover.	A320		POMEGRAN ATE LEASING CO	Australian VH	VH-VGD VH-VZY	AEROPLA NE	A320-232

Tue, 14 Dec 2021		Unassigned				30 NM 229 degrees			During approach, the aircaft encountered a tail wind. The aircraft landed hard and overran the runway resulting in minor damage to the aircraft.				Unknown		ULTRALIG HT	A-22
18 28 37 +1100 Mon, 10 Jan 2022 16 40 09	OA2021- 05454 OA2022-	Occurrence s Eastern -	05/09/2021	Incident	TAS	from Hobart Aerodrome 0 km 0 degrees from Hobart	-43.163064	146.994672			s 47G		Registration Type Unknown Registration	24-5200 24- 5200 VH-YWE VH	HT AEROPLA NE	22 VALOR
+1100 Tue, 30 Nov 2021	05728 OA2021-	CMT 1	11/10/2021	Incident	TAS	Aerodrome 0 km 0 degrees	-42.836111	147.510278	During landing, the aircraft struck a	B738		LTD. SHORT HAUL 2017	Type Australian VH	YWE	NE	737-800
05 52 35 +0000	05068	Eastern - CMT 1	22/10/2021	Incident	TAS	from Hobart Aerodrome	-42.836111	147.510278	Richard's pip t. During cruise, the right windshield	B738		NO. 2 PTY LTD	Australian VH Aircraft	VH-YWA	NE	737-800
Fri, 3 Dec 2021 05 58 21 +0000	OA2021- 05162	Western - Pool	03/11/2021	Incident	TAS	150 NM 90 degrees from Hobart Aerodrome	-42.7857243	150.906299	shattered and the crew diverted the aircraft to Hobart. Engineers replaced the windshield	CL60		LEIDOS SAR SERVICES PTY LTD	Australian VH Aircraft	VH-XNE	AEROPLA NE	CL-600- 2B16
Thu, 2 Dec 2021 06 17 +0000	OA2021- 05278	Sydney - CMT 1	22/11/2021	Incident	TAS	62.7 km 355 degrees from Hobart Aerodrome	-42.273666	147.447891	During cruise, the crew observed different readings on the left and right altimeters and diverted the aircraft to Melbourne. Engineers replaced the no. 2 digital air data computer.	B733		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-XML	AEROPLA NE	737-376
Mon, 10 Jan 2022 06 11 23 +0000	OA2021- 05546	Western - Pool	17/12/2021	Incident	TAS	near Hobart Aerodrome	-42.836111	147.510278	During approach, the autopilot disconnected uncommanded and the crew received multiple warnings including a BUS DC R OFF warning and momentary stick shaker. The engineering inspection did not reveal any faults w th the electrical system.	B712		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-YQX	AEROPLA	717-200
Tue, 11 Jan 2022 05 57 21 +0000	OA2021- 05626	Eastern - CMT 1	18/12/2021	Incident	TAS	near Hobart Aerodrome		147.510278	During approach, the crew received a steer fail warning. After landing, the crew stopped the aircraft on the taxiway and reset the system with operations returning to	E190		BRAVO AIRLINES PTY LIMITED	Australian VH		AEROPLA NE	
Tue, 8 Mar 2022 16 40 08	OA2021-	Southern -							During take-off, the aircraft struck a pacific gull and the pilot rejected			AIRLINES OF TASMANIA	Australian VH		AEROPLA	
+1100 Fri, 14 Jan 2022 05 48 40 +0000	06391 OA2022- 05752	Southern -	28/12/2021 08/01/2022	Incident Serious incident	TAS	Cambridge 30 NM 230 degrees from Hobart Aerodrome		147.474722	the take-off. During aerial agricultural operations, the helicopter's tail rotor struck a powerline resulting in minor damage.			s 47F	Aircraft Unknown Registration Type	vh-wzm s 47F	NE HELICOPT ER	404 AS 350 B3
Wed, 12 Jan 2022 05 52 39 +0000		Northern -	09/01/2022	Incident		80 NM 360 degrees from Hobart Aerodrome		147.510278	During approach, the crew received a low oil pressure indication and shut down the no. 1 engine as a precaution. Engineers suspect a incorrectly seated seal resulted in the low oil pressure indications.			VEE H AVIATION PTY LTD.	Australian VH Aircraft	VH-VED	AEROPLA	340B
	OA2022- 00722	Eastern - CMT 1	14/01/2022	Incident	TAS	Hobart Aerodrome	-42.836111	147.510278	During landing, the aircraft struck a bronze brush-wing pigeon resulting in minor damage to the right engine			STELLAR UK 1 LIMITED		VH-VUG	AEROPLA NE	737-8FE

Thu, 21 Apr 2022					Flight controls Missed					During approach, the crew received an abnormal flap indication and conducted a missed approach. The crew proceeded to conducted a flapless approach. The engineering inspection revealed the left wing lower slat drive cylinder had		7G	QANTAS				
	OA2022- 01296	Western - Pool	04/04/2022	Incident	approach / Go-around	TAS	Hobart Aerodrome	-42.836111	147.510278	failed.	B712		AIRWAYS LIMITED	Australian VH Aircraft	VH-NXI	AEROPLA NE	717-200
					-					Descending							
Wed, 4 May							9 NM 315			through 3,000 ft,							
2022 16 40 26	OA2022-	Southern -			Landing gear /		degrees from Hobart			the crew received an unsafe landing			AIRLINES OF TASMANIA	Australian VH		AEROPLA	
+1000 Mon, 16 May	01546	CMT 1	21/04/2022	Incident	Indication	TAS	Aerodrome	-42.7299244	147.366365		BE76		PTY LTD VA	Aircraft	VH-MKH	NE	76
2022										During take-off, the aircraft struck			BORROWER				
	OA2022- 01859	Eastern - CMT 1	15/05/2022	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.836111	147.510278	a masked lapwing (bird).	B738		2019 NO. 2 PTY LTD	Australian VH Aircraft	VH-YIG	AEROPLA NE	737-8FE
Wed, 25 May 2022										During landing, the			CIT				
16 40 12	OA2022-	Eastern -					Hobart			aircraft struck a			AEROSPACE			AEROPLA	
+1000	01974	CMT 1	23/05/2022	Incident	Birdstrike	TAS	Aerodrome	-42.836111	147.510278	robin.	B738		LLC	Aircraft	VH-YFY	NE	737-800
	042022-	Eastern -			Engine failure or malfunction Diversion /		near Hobart			During cruise, the no. 2 engine stopped responding to crew commands. The crew returned the aircraft to Hobart and shut down the engine. Engineers were not able to replicate the fau t.				Australian VH		HELICOPT	44550
	02216	CMT 1	12/06/2022	Incident	Return	TAS	Aerodrome	-42.836111	147.510278		B412		LIMITED	Aircraft	VH-XCY	ER	412EP
Tue, 26 Jul 2022										During landing, the aircraft struck a			QANTAS				
16 40 10	OA2022-	Southern -	14/07/2022	Incident	Disdatsika	TAC	Hobart	40.0001111	447 540070	plover masked lapwing.	4204		AIRWAYS	Australian VH		AEROPLA	4224 224
+1000	02680	CMT 1	14/07/2022	Incident	Birdstrike	TAS	Aerodrome	-42.836111	147.510278	During climb, the	A321		LIMITED	Aircraft	VH-VWT	NE	A321-231
	OA2022- 02892	Southern - CMT 1	27/07/2022	Incident	Loss of separation Loss of separation Operational non- compliance	TAS	near Hobart Aerodrome	-42.836111	147.510278	Bell 412EP climbed above their assigned leve resulting in a loss of separation with the converging Beechcraft 76.	BE76		s 47F	Unknown Registration Type	s 47F	AEROPLA NE HELICOPT ER	76 412EP
	OA2022- 02964	Southern - CMT 1	27/07/2022	Incident	Fumes	TAS	43.1 km 29 degrees from Hobart Aerodrome	-42.49498	147.761307	During descent, fumes were detected in the cabin. The engineering inspection revealed oil contamination on the APU inlet.	A320		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-VFV	AEROPLA NE	A320-232
	OA2022- 02976	Western - Pool	28/07/2022	Incident	Flight below minimum altitude Operational non- compliance	TAS	11 NM 119 degrees from Hobart Aerodrome	-42.9248086	147.728525	During descent, the crew inadvertently descended below the minimum safe altitude at waypoin PIDOS.	1 B712		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-NXE	AEROPLA NE	717-200
	OA2022- 04911	Sydney - CMT 1	24/10/2022	Incident	Incorrect configuratior Ground proximity alerts / warnings	TAS	1 NM 300 degrees from Hobart Aerodrome	-42.8277737	147.490663	During approach, the pilot did not select the correct flap setting resulting in an E/GPWS TOO LOW FLAP alert.	BE20		s 47F	Australian VH Aircraft	s 47F	AEROPLA NE	B200C
										During take-off,			QANTAS				
	OA2022- 04759	Western - Pool	27/10/2022	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.836111	147.510278	the aircraft struck a Richard's pipit.	B712		AIRWAYS LIMITED	Australian VH Aircraft	VH-NXO	AEROPLA NE	717-200
										During disembarkation,							
	OA2022- 04938	Southern - CMT 1	09/11/2022	Incident	Fumes	TAS	Hobart Aerodrome	-42.836111	147.510278	disembarkation, fumes were detected in the flight deck and cabin. During take-off, fumes were detected in the	A320		UMB BANK, NATIONAL ASSOCIATIO N	Australian VH Aircraft	VH-VQE	AEROPLA NE	A320-232
Mon, 5 Dec 2022 16 40 14	OA2022- 04435	Western - Pool	22/11/2022	Incident	Fumes	TAS	Hobart Aerodrome	-42.836111	147.510278	cabin. The engineering inspection revealed oil wetting on the no. 2 engine.	B712		QANTAS AIRWAYS LIMITED	Australian VH Aircraft	VH-NXR	AEROPLA NE	717-200
+1100										During approach,			CIT				
		-															
	OA2022- 05097	Eastern - Pool	28/11/2022	Incident	Birdstrike	TAS	Hobart Aerodrome	-42.836111	147.510278	the aircraft struck a black cockatoo.	B738		AEROSPACE LLC	Australian VH Aircraft	VH-YFY	AEROPLA NE	737-800