

L12/B13  
38

P614 copy 1.  
AUS

~~P016~~  
AUS

(38)

A.A.E.C. LIBRARY Bibliography. No 38.



Decontamination.

DECONTAMINATION

1. B.542.1 57/805  
DUN III Hot laboratory operation and equipment Vol.III, ed. by John P. Dunning and Bruce R. Prentice.
2. USAEC NYO-4682-A Fallout countermeasures for AEC facilities, by Alfred J. Breslin and Leonard R. Solon, Dec. 1955.
3. AWRE - O-42/55 Physicochemical investigations into the absorption and removal of radioisotopes from textiles (radio-logical decontamination). Part I. Polyvalent cations on cotton, by D.G. Stevenson.
4. USNRDL-TR-60 Effects of elevated temperatures on the properties of Portland cement mixtures related to surface removal and decontamination, by R.H. Heiskell and others. 25th August, 1955.
5. USAEC - IDO-14379 Effectiveness of various solutions for decontaminating stainless steel, lead and glass, by J.B. Huff, 24th May, 1956.
6. USAEC - KAPL-1406 High-level contamination control and waste disposal, by R.F. Stearns, 1st November, 1956.
7. USAEC - ORNL-2058 Decontamination of the ORNL thorex pilot plant, by K.H. McCorkle and W.R. Winsbro. 25th July, 1956.
8. USAEC - HW-38218  
Rev. A Study of the effectiveness of decontaminating agents on contaminated protective clothing, by J.L. Norwood. 29th July, 1955.
9. P 614.898 55/325 U.S. Dept. of Commerce. NBS Handbook 48. Control and removal of radioactive contamination in laboratories.
10. USAEC - Y-964 Decontamination: a literature search, by Rosalie L. Curtis. 19th May, 1953.
11. AERE C/R 958 Symposium on the handling of radioactive and toxic substances. Buckland House, September, 1951. Ed. by G.R. Hall.
12. USAEC - ORNL-600 Review and outline of present laundry procedure at ORNL, by H.J. McAlduff, Jr.
13. USAEC - UR-108 The Removal of uranium compounds from cloth, a laundry problem, by A.B. Carlson and W.F. Neuman. 8th May, 1950.
14. USAEC - NYO-4990 An Evaluation of laundering agents and techniques used in the decontamination of cotton clothing, by Albert P. Talboys and Eugene C. Spratt. 1st March, 1954.
15. AERE C/R 286 Removal of radio-active contamination from various surfaces, by Miss E.S. Busk and K.D.B. Johnson. December, 1948.
16. AERE HP/M 93 Tests on polyvinyl chloride/acetate copolymer coated papers for use as bench coverings in radioactivity laboratories, by R.C. Chadwick, 1955.
17. AERE HP/M 18 Decontamination of metal articles by an electrolytic process, by K.D. Outteridge. 16th August, 1950.
18. AERE HP/M 54 Tests on surface finishes, by R.C. Chadwick. 20th October, 1953.

19. Nucleonics, 12 (8)  
Aug. 1954. p.12-15.
20. USAEC - HW-42030
21. IGRL-IB/R 27  
Radioactive decontamination procedures and equipment - bibliography.
22. Industrial Chem.  
33 (393) Nov. 1957.  
p.543.
23. Reprints, etc.  
614.898  
56/1071  
Medicine Illustrated 8 (11) November, 1954.  
The protection of personnel working with radioactive materials and the disposal of contaminated waste, by H.J. Dunster. p.731.
24. AERE HP/L 23