



Australian Government

Australian Radiation Protection and Nuclear Safety Agency

R16/05548

12 May 2016

Mark Wallis
Business Infrastructure Services
CSIRO
Private Bag 2
Glen Osmond SA 5064

Dear Mr Wallis

Inspection of CSIRO Business Infrastructure Services – Source Licence S0013

I attach a copy of the report R16/05292 relating to the inspection of CBIS Woomera conducted between the 27th and 29th April 2016.

The inspection found no areas of non-compliance. However, a number of performance deficiencies were identified which, if properly addressed, will support performance improvement. It is expected that actions to address these performance deficiencies will be taken in a timely manner.

ARPANSA understands that international best practice in relation to storing legacy waste is to fully characterise the drums so that the contents are accurately known. It is understood that this task will take time. I request that you develop a plan for undertaking the characterisation of the drums and submit this to ARPANSA for approval by the end of this financial year.

Please note that the inspection report will be published on the ARPANSA website.

Yours sincerely

s 47F - privacy

Jack Dillich
Acting CEO
ARPANSA

Encl: Inspection Report R16/05292

cc via email: neil.webster@csiro.au